SYSLOG Error: "WARNING: 018r27 ATTN: FAN <X> warning limit reached @ 0 RPM

Published 08/20/2001

Symptom(s):

```
SYSLOG Error: "WARNING: 018r27 ATTN: FAN

    warning limit reached @ 0 RPM
```

Fact(s):

```
SGI Origin 3000
IRIX 6.5.X
SGI Onyx 3000
```

SGI Solution:

```
To troubleshoot, make sure the L1 is running the latest firmware.   There were previous bugs  795454 and 814192.  The L1 should be
running firmware version 1.3.10 or greater.
a) At the L1 prompt type the command "ver" to list the firmware.
L2 version:
b) You can also use the command "flash status" to view the flash for all controllers.
01c10:
Flash image B currently booted
Image   Status          Revision        Built
-----   ------------    ------------    ------
A       valid                   08/08/2001 07:50:03
B       default         08/08/2001 07:50:03

If the firmware is up to date then it is most likely a hardware error in the fan that requires a replacement.
```

Cause(s):

```
The fan has either failed or is starting to fail.
```

Answers others found helpful

- Fan 0 warning limit reached at 0 rpm - Identifying Fan 0 on an Onyx 350
- PCI fan is failing and can't determine which is fan 3 and which is fan 4.

Additional Details

Creation Date	05/09/2001 07:04 AM
Last modification	01/15/2016 04:29 PM
Published Date	08/20/2001
Products	• Servers and Clusters • SGI Origin/Onyx • Origin/Onyx Server • Software • Legacy Software • Operating Systems • IRIX • Workstations • SGI Tezro • O2 • Octane
Categories	• Knowledgebase • Technical Solution